

September 11<sup>th</sup>, 2023

## Product Change Notification

<b>PCN #:</b>	AM20230911-1
<b>Issue Date:</b>	September 11 <sup>th</sup> , 2023
<b>Products series affected:</b>	AM10CW-NZ and AM10EW-NZ series
<b>Product list:</b>	AM10CW-4803S-NZ, AM10CW-4803S-NZ-ST, AM10CW-4803S-NZ-STD, AM10EW-4803SH30-NZ, AM10EW-4803SH30-NZ-ST and AM10EW-4803SH30-NZ-STD
<b>Effective Date:</b>	All specified products above, and shipping from Aimtec factories as of the issue date of this PCN.
<b>Description of change:</b>	<p>The parts listed above have a <u>change in the transient recovery deviation</u>. The transient recovery deviation has been increased from <u>3%/5% (Typ./Max.) to 5%/8% (Typ./Max.)</u>.</p> <p>No other changes to the product's performance and specifications have been made.</p>
<b>Reason for change:</b>	This change has been implemented to increase manufacturing efficiency in our production line.
<b>Customer Impact:</b>	Certain customers may be impacted by the changes in the transient recovery deviation. Aimtec recommends reviewing the datasheet and testing the parts as necessary.
<b>Package Diagram:</b>	N/A