BeagleBone Black Rev D Update

For revision D, the HDMI framer has been updated due to NXP stopping manufacturing of the TDA19988. We've replaced it with an ITE IT66122.