

# Aquasol 4018



Page 1

## Lead-free, high activation, water soluble solder wire

### **Description:**

Interflux Aquasol 4018 for lead-free alloys is a solder wire with water soluble flux residue.

It is highly activated for increased wetting on surfaces that are difficult to solder or degraded and oxidised surfaces.

Aquasol 4018 residue must be cleaned. Cleaning is easily done with demi water of 35— 45°C (95°F— 114°F) with or without the aid of a saponifier.

Aquasol 4018 can be used in both hand soldering and automated soldering processes.

Aquasol 4018 solder wire contains halogens and is classified as OR H1 according to IPC and EN-standards.



Products pictured may differ from the product delivered

# RoHS



Click for Interflux' ecological profile

## **Key properties**

- Water soluble flux residue
- High wetting power on surfaces that are difficult to solder.
- Suitable for automated soldering

# **Availability**

Technical Data Aquasol 4018

Ver: 5.0 09-01-24

S.A. INTERFLUX<sup>®</sup> ELECTRONICS N.V - Eddastraat 51 - BE-9042 Gent - Belgium tel.: +32 9251 49 59 - www.interflux.com - info@interflux.com





# Aquasol 4018



Page 2

# **Work Instructions**

#### **Manual soldering**

The advised working temperature is between 320°C and 390°C. For more dense metals like Nickel, the temperature may be elevated to 420°C. The use of a good soldering station is important. Use a soldering station with a short response time and with enough power for your application. Choose the correct soldering tip: to reduce the thermal resistance, it is important to create a large contact area with the surfaces to be soldered. Heat up both the surfaces simultaneously. Slightly touch with the solder wire, the point where soldering tip and the surfaces to be soldered meet (the small quantity of solder ensures a drastic lowering of the thermal resistance). Add subsequently without interruption, the correct amount of solder close to the soldering tip without touching the tip. This will reduce the risk on flux spitting and premature flux consumption!

Post solder residue needs to be cleaned. This can be done with demi water of 35— 45°C (95°F— 114°F) with or without the aid of a saponifier.

# Handling

#### **Storage**

Store the solder wire in a clean environment at ambient temperature.

### **Handling**

To avoid spool and wire damage, handle package with care.

#### Safety

Please always consult the safety datasheet of the product.

## **Packaging**

The standard packaging is a 500g spool.

Other spool sizes upon request



Ver: 5.0 09-01-24



# Aquasol 4018



Page 3

# Test results Conform EN 61190-1-3(2007) and IPC J-STD-004(A)

Property	Result	Method
Chemical		
flux designator	OR H1	J-STD-004A
	F-SW 25	DIN 8511
	2.1.2	ISO 9454
% halide content	>2%	J-STD-004A IPC-TM-650 2.3.35
Environmental		
SIR test	pass (cleaned)	J-STD-004 IPC-TM-650 2.6.3.3
qualitative corrosion, flux	pass (cleaned)	J-STD-004A IPC-TM-650 2.6.15
electro chemical migration	pass (cleaned)	J-STD-004A IPC-TM-650 2.6.14.1

Trade name: Aquasol 4018 Lead-free, Water Soluble Wire

## Disclaimer

Because Interflux Electronics N.V. cannot anticipate or control the many different conditions under which this information and our products may be used, we do not guarantee the applicability or the accuracy of this information or the suitability of our products in any given situation. Users of our products should make their own test to determine the suitability of each such product for their particular purposes. The product discussed is sold without such warranty, either express or implied.

Copyright:

**INTERFLUX®** ELECTRONICS N.V

Latest version of this document on:

www.interflux.com



S.A. INTERFLUX $^{\circ}$  ELECTRONICS N.V - Eddastraat 51 - BE-9042 Gent - Belgium tel.: +32 9251 49 59 - www.interflux.com - info@interflux.com

