



晶采光電科技股份有限公司  
AMPIRE CO., LTD

4F., No.116, Sec. 1, Sintai 5th Rd., Sijhih City, Taipei County 221, Taiwan (R.O.C.)

Notification of Product			
Issue Date	Last order date	Last shipping date	Notification No.
2024/08/07	N/A	N/A	X

This is to advise you the following products information

Product ID (Description)	
AM-320240NTMQW-T00H-A (5.7")	AM-320240NTMQW-T00H-B (5.7")
AM-320240NTMQW-T09H-A (5.7")	AM-320240NTMQW-T09H-B (5.7")
AM-320240NTMCW-T30H-A (5.7")	AM-320240NTMQW-T30H-C (5.7")
AM-320240NTMQW-T30H-D (5.7")	AM-320240NTMQW-T32H (5.7")
AM-320240NTMQW-T38H (5.7")	AM-320240NTMQW-T30H-E (5.7")
AM-320240NMZQW-T00H-A (5.7")	AM-320240NMZQW-T30H-E (5.7")
AM-320240NTMQW-TW0H-A (5.7")	AM-320240NMZQW-TW0H (5.7")
AM-320240NTMQW-TW4H-A (5.7")	AM-320240NMZQW-TW4H-A (5.7")
AM-320240N6TMQW-TW4H (5.7")	AM-320240N6TMQW-TW4H-A (5.7")
AM-320240NTMQW-TW9H (5.7")	


Description of change
Due to the 6PIN connector has been EOL. It's for RTP connections. We change the design from connector to soldering. There is no any affection of the electronic, mechanical feature. Please check with Ampire sales for new part no. and samples.





# 晶采光電科技股份有限公司 AMPIRE CO., LTD

4F., No.116, Sec. 1, Sintai 5th Rd., Sijhih City, Taipei County 221, Taiwan (R.O.C.)

Current



New



In case of further questions, please contact your contact. If you do not ask a new sample for approval, Ampire confirms that you approve the Ampire replaced parts of above items. All the replaced parts are approved by Ampire thus if you need a new sample for approval, please ask your contact.